



DRIVING WORLDWIDE BUSINESS EXCELLENCE

## Aerospace APQP and PPAP Series Design Tools Including SFMEA / DFMEA and Associated Tools



**Training Duration : 2 days**

CONSULTING \* TRAINING \* SOFTWARE

USA \* CANADA \* CHINA \* EUROPE \* INDIA \* MALAYSIA \* MEXICO  
MIDDLE EAST \* UAE \* SINGAPORE \* THAILAND

[www.omnex.com](http://www.omnex.com)

# Aerospace APQP and PPAP Series

## Design Tools Including SFMEA / DFMEA and Associated Tools

Training Duration : 2 days

### Seminar Content

This two-day hands-on seminar is intended to offer insight into, and hands-on experience with, the linkages between various aspects of the Advanced Product Quality Planning (APQP) process. Specifically, the development and linkage of Block Diagrams, System and Design FMEAs and Design Verification (Test) Plans (DVPs) are addressed.

SFMEAs are performed during the Design phase of APQP for Risk Management and Prevention. SFMEAs are used to identify Special Requirements, Critical Items and Key Characteristics to assist in the flow-down to sub-assemblies and components.

### Who Should Attend

- Program Managers
- Project Managers
- Quality Managers
- Design Engineers
- APQP Team Members
- All other Risk Management personnel

### Recommended Training and/or Experience

Participants should possess a working knowledge of quality systems and methodologies.

### Seminar Materials

Each participant will receive a seminar manual and a workbook including all team breakout exercises.

### Seminar Goals

- Provide a hands-on approach to S/DFMEAs and their relationship to program deliverables and status reporting
- Provide the competencies needed to introduce new products and processes smoothly
- Gain knowledge and understanding in:
  - Block Diagrams and Interface Matrix
  - Linkages between Block Diagrams, SFMEAs, DFMEAs, DVP and other design tools
  - Linkages between PFMEAs and S/DFMEAs
  - Using FMEA as an analytical process
  - S/DFMEAs and DVPs

### Seminar Outline

- FMEA Introduction
- Putting an FMEA Together
- DFMEA Prerequisites
  - Breakout Exercise: Customers & Functional Requirements
  - Breakout Exercise: Boundary Diagrams
- Developing the DFMEA
  - Breakout Exercise: Starting the DFMEA Form
  - Breakout Exercise: Failure Modes
  - Breakout Exercise: Design Causes
  - Breakout Exercise: Design Control
  - Breakout Exercise: Effects, Severity and Action Plans
- DFMEA – Component Level
  - Breakout Exercise: Developing a Component DFMEA
- Test Planning and Reporting

CONSULTING \* TRAINING \* SOFTWARE



## GLOBAL HEAD QUARTERS

### OMNEX INC

Global Head Quarters,  
315 E. Eisenhower Parkway,  
Suite 214, Ann Arbor, MI 48108, USA  
Phone: (734) 761-4940  
Fax: (734) 761-4966  
Email: [info@omnex.com](mailto:info@omnex.com)  
Web: [www.omnex.com](http://www.omnex.com)

## MAIN REGIONAL OFFICES

### OMNEX CANADA

Email: [info-ca@omnex.com](mailto:info-ca@omnex.com)

### OMNEX CHINA

Email: [info-cn@omnex.com](mailto:info-cn@omnex.com)

### OMNEX EUROPE

Email: [info-eu@omnex.com](mailto:info-eu@omnex.com)

### OMNEX INDIA

Email: [info-in@omnex.com](mailto:info-in@omnex.com)

### OMNEX MALAYSIA

Email: [info-my@omnex.com](mailto:info-my@omnex.com)

### OMNEX MEXICO

Email: [info-mx@omnex.com](mailto:info-mx@omnex.com)

### OMNEX MIDDLE EAST

Email: [info-me@omnex.com](mailto:info-me@omnex.com)

### OMNEX UAE

Email: [info-ae@omnex.com](mailto:info-ae@omnex.com)

### OMNEX SINGAPORE

Email: [info-sg@omnex.com](mailto:info-sg@omnex.com)

### OMNEX THAILAND

Email: [info-th@omnex.com](mailto:info-th@omnex.com)